



# TECHNICAL SPECIFICATION

Technical Service Department,  
JSP Ltd., Worsham Mill, Minster  
Lovell, Oxford, OX29 0TA  
Tel.: 01993 824000  
Fax: 01993 824422

## Surefit Wire Gauze Visor

### Conformity:

Meets the requirements of EN 166:  
1996.

Placed EC Certificate Number 2406,  
issued by BSi Product Certification.

### Size & Weights:

**Size** 530 – 620mm (6½ - 7⅞)

**Weight** 0.20Kg  
(Weight is approx)

### Performance:

20cm Wire Gauze

Offers general robustness against  
particles at 12m/s.

**Markings: EN1731 1.S**



### Instructions For Use:

In use ensure that the Faceshield fits comfortably and securely on the head. Ensure that a suitable visor has been fitted with the protective film removed from it. Ensure the visor is in place before entering the hazard area.

### Limitations Of Use:

Protection will only be offered if the visor carrier and a visor are fitted correctly to a suitable Industrial Safety Helmet with the helmet attachment kit. If the visor becomes scratched or damaged it should be replaced. Do not apply paint, solvents, adhesives or self-adhesive labels, except in accordance with instructions from the manufacturer. The Industrial Safety Helmet harness, when in contact with the skin may cause allergic reactions to susceptible individuals. If this occurs leave the hazard area, remove the faceshield and seek medical advice.

### Notes:

*i. The visor is not suitable for use with chemicals – if you are unsure contact your supplier or JSP for help and advice.*

### Cleaning & Maintenance:

The visor may be cleaned with soap and warm water and dried with a soft cloth. Do not clean with chemical or abrasive cleaners. Store out of direct sunlight, away from chemicals and not exposed to extremes of temperature.